Spelsbury Parish Council

Checklist for Play Equipment – Spelsbury Playground

Inspector Name: Anne Ogilvie
Inspection Date: 29 April 2024
Inspection Time: 5.05 pm

Section	٧/ ×	Action Necessary	Date Completed
Site condition			
No weeds, planting cut back and not overhanging play area	Х	Some overhanging branches	
Site free from litter, debris and unauthorised items	Х	Area of cut hedging on site	
Site free from animal fouling	√		
No glass or sharp objects in playground	✓		
General surface area free from trip hazards	✓		
Adequate site drainage	✓		
Signage			
Present, legible and securely fixed	✓		
Seating			
Undamaged and in good condition	Х	Old seat needs to be removed	
Litter bin			
Completed and undamaged	√		
Securely fixed against movement	√		
Not full/overflowing	√		
Accessible	✓		

Section	٧/ ×	Action Necessary	Date Completed
Swings – one bay: one standard, one cradle			
All supports present, secure and free from decay at ground level	√		
All metalwork undamaged and free from corrosion	√		
Working properly without undue noise	√		
Chains intact and in good condition with less than 40% wear	✓		
Swing seats unbroken with no exposed metal	X	Cradle swing has wear damage – cracking of undersurface, middle verticals are damaged – not logged as an issue on the annual independent inspection report - MONITOR	
Seats fixed securely	✓		
Grass surface level, not causing trip hazards	Х	Ground is uneven under standard swing	
Rotating seat unit (roundabout)			
Undamaged and level	✓		
Revolves smoothly and noiselessly	√		
No protruding bolts	√		

Section	٧/ ×	Action Necessary	Date Completed
Rotating seat unit (roundabout)			
Clear of rubbish underneath	√		
Safety surface undamaged and fixed securely with undue gaps	✓		
Safety surface level with surrounding ground, not causing trip hazards	√		
No weeds present in safety surface	Х	Few weeds in safety surface	
Seesaw			
Undamaged	Х	Seat areas are rusting. Paint is lifting	
Securely fixed and level	✓		
Moves smoothly and noiselessly	Х	Noise when moving	
No protruding bolts	✓		
Clear of rubbish and obstructions	✓		
Grass surface level, not causing trip hazards	Х	Surface uneven	
MUGA End			
Securely fixed	√		
Undamaged	✓		
Level surface surrounding target	√		
Any Other Observations			